# Contents

Robert Service Senior Public School	1
Introduction	3
Summary	3
Exterior	3
Interior	4
Other Information	4
Legend	5
Robert Service Senior Public School Site Plan	6
Using the Accessibility Drawings	7
Introduction	7
Entrances	7
Interior Access	
Washrooms	
Fire Safety Planning	
Accessibility Designations	ų .
Accessible	
	10

Date of Update: May 2022

Introduction

The information provided below is based on a survey conducted of Robert Service Senior

Public Schol in June 2014 and is for reference only. All visitors to the building should contact

the main office in advance to verify access and arrange for necessary accommodations.

This site has been designated Not Accessible. For definitions of designations and instructions

on how to use the accessibility drawings attached, please see page 5

Summary

The school is not accessible. There are no entrances equipped with powerated doors or

accessible washrooms. Floor access is also limited to the first floor. In addition, some

specialized rooms are in sunken areas of the first floor

Exterior

Parking: There is one accessible parking space near the main entrance.

Pathways: Most exterior routes are accessible. The route to the accessible parking space has

cracking in the pavement, and the curb ramp leads directly into a parking space, which may

be obstructed by a parked vehicle.

Entrances: None of the entrances are designated accessible or are equipped with a power

operated door. However, all entrances to the building are either level or sloped

Date of Update: May 2022 Page3 of 11

### Interior

Floor Access The school does not have an elevator, making the second floor is inaccessible. Additionally, there are no ramps to address the sunken areas which house the cafeteria and the library.

#### Specialized Rooms

Main Office: Somewhat accessible; no powerperated door.

Library: Not accessible; in sunken area

Cafeteria: Not accessible; in sunken area

General Purpose/Gymnasium: Somewhat accessible; no powerperated door.

Auditorium: Refer to cafeteria

Pool: N/A

Washrooms: There are no accessible washrooms in the school

# Other Information


No visual fire alarms.

No markings on stairs for people with low vision.

Date of Update: May 2022 Page4 of 11

Bus stop

### Legend




Date of Update: May 2022 Page5 of 11

Power-operated door

# Robert Service Senior PublicSchool Site Plan

Facility#:0497



Date of Update: May 2022

Page6 of 11

# Using the Accessibility Drawings

#### Introduction

The TDSB has produced drawings to show accessible features as well as barriers for each of its buildings. This information will be useful for students, staff, parents, and community members some of whom have physical disabilities and need to know the features and barriers of our buildings.

The current Ontario Building Code (OBC) is generally used as the basis for the accessibility features included in the drawings. However, features that do not fully conform to current regulations are nevertheless identified. A legend noting features such as people rated doors and elevators accompanies each set of drawings.

#### **Entrances**

Entrancenumbers are provided on the drawings for reference and corresponditumbers posted inside and outside each public entrance. Entrance numbers have an associated icon:

(denoting a flush condition) o (denoting a stepped condition). The approach to a flush entrance may be ramped, sloped, or flat, but has no appreciable height differential at the doorway. A stepped entrance is one with an appreciable step not compliant with OBC requirements for level access. Powerperated doors, if present, are identified with icon.

To ensure student safety and security, elementary school buildings have a locked door policy. Visitors are direted to enter through the building's main entrance door after contacting the main office using the intercom provided. Where applicable, the drawings will indicate a recommended path to the main entrance doors (i.e., an arrow pointtoothe main door).

Date of Update: July 2021 Page7 of 11

A recommended path has not been shown to the main entrance where:

• the main entrance is not level, or

the path to the main entrance has a barrier.

If a level path exists between the parking lot and a nearby level entrance, the path to the parking lot from that doorway is indicated on the drawings regardless of whether there is a power-operated door present.

At secondary schools, intercoms are not present. Usually the doors closest to the parking lot or the main entrance doors are open during school operating hours. Recommended paths are shown to these doors if the path and doorway are level and there is a people rated door present.

**Interior Access** 

The 1st floor (at grade) of the school is assumed to be accessible, even if there is no recommended path to the building. Access to floors other than the 1st floor is indicated by an icon denoting an elevato or ramp if present. Stairway locations whighlighted on the drawings to indicate access to floor levels; this information is included for individuals who do not require the use of a mobility device.

The main office, communityuse areas, and rotatio program areas are abelled on the floor plans for ease of navigation. Various instructional, administrative, and service rooms are also indicated.

Doors at corridors and stairwells are marked on the drawings. If a people rated door is not present (icon is absent), the doors may present a bartoes ome individuals. Powe operated door devices may be pushoutton, hold-open, or motion detection types.

Date of Update: July 2021 Page8 of 11

Washrooms

Washrooms that are moderately to highly accessible are recommended and identified by a

icon. The respective use for gender is also pinded; male, female, or universal is denoted

by a corresponding letter M, F or M/F.

Fire Safety Planning

Areas of Safe Refuge are locations where persons with disabilities begin their vedtesalent

stage of evacuation upon fire alarm. These have been identified on the drawing where

present. They are located at EXITairwell landings on floors other than those at grade level,

where the stairwell doors latch. Information regarding the use of Areas of Safe Refuge is

found within each site's Fire Safety Plan.

**Accessibility Designations** 

The following definitions of acessibility at TDSB sites focus on mobility. Where

accommodations exist for people with limited sight and/or hearing, or other types of

disabilities, they will be described on each site's accessibility profile. Because each person's

requirements are uniquethe designation is to be used as a guideline only.

Date of Update: July 2021 Page9 of 11

### Accessible



A person who uses a mobility device can enter and move through the building to access all or most areas without assistance or with minimal assistance. To be deemed accessible,

- the building can be accessed by a barrifeee path,
- there is at least one level entry at a main entrance operated by a power-operated door,
- there is at least one barriefree universal washroom on the main floor, and
- where the building has more than one level, there is an elevating device (such as a lift or passenger elevator), but access on all floors may be limited.

### Somewhat Accessible



Somewhat accessible is our designation for buildings that are not fully accessible, but they are also not completely inaccessible. They have some features that make them partially accessible.

In a somewhat accessible building, a person who uses a mobility device can enter and move through the main floor of the building with minimal assistance. Barrieree access to other floors is not guaranteed.

Generally speaking, to be deemed somewhat accessible,

- the building can be accessed by a barrifere path and there is at least one level entry to the building, which may or may not have power-operated doors, and
- there is at least one washroom that is somewhat barrier free

Date of Update: July 2021 Page10 of 11

### Not Accessible



A person who uses a mobility device will either not be able to access the building or will require significant assistance. To be deemed not accessible,

- the building cannot be accessed by a barrifere path,
- there are no main entrances that are level, or
- there are no washrooms that are as a minimum, somewhat accessible.

Date of Update: July 2021 Page11 of 11