

# **Chief Dan George Public School**

185 Generation Blvd, Scarborough, ON M1B2K5

(416) 396-6150

Accessibility survey date: May 2015



For public: summary and site plan

Date of Update: July 2021 Page 1 of 11



# **Contents**

C	hief Dan George Public School	1
	Introduction	. 3
	Summary	. 3
	Exterior	. 3
	Interior	. 4
	Other Information	. 4
	Legend	. 5
	Using the Accessibility Drawings	. 7
	Introduction	. 7
	Entrances	. 7
	Interior Access	. 8
	Washrooms	. 9
	Fire Safety Planning	. 9
	Accessibility Designations	. 9
	Accessible	10
	Somewhat Accessible	10
	Not Accessible	11



### Introduction

The information provided below is based on a survey conducted of Chief Dan George Public School in May 2015 and is for reference only. All visitors to the building should contact the main office in advance to verify access and arrange for necessary accommodations.

Chief Dan George Public School has been designated **Accessible.** For definitions of designations and instructions on how to use the accessibility drawings attached, please see page 7.

# **Summary**

This school is accessible. Entrance #6 is equipped with a power-operated door. There is also an elevator to access the second floor. The interior of the school is level on both floors.

Additionally, there are seven accessible washrooms available.

### **Exterior**

**Parking:** This school has one designated accessible parking space near entrance #6. Entrance #6 is level and equipped with power-operated doors.

**Pathways:** Most exterior entrances are barrier free but the route to the playfield and the sidewalk are not equipped with power-operated doors.

**Entrances:** Entrances #1, #2, #4, #5 and #6 are level and entrance #3 is sloped. However, entrance #2 is not a main entrance since it goes through the kindergarten cupboard locker area. Entrance #6 is also equipped with power-operated doors.

Date of Update: July 2021 Page 3 of 11



### **Interior**

**Floor Access**: There are two floors in this school and all the interior routes on both floors are level. There is also an elevator.

#### **Specialized Rooms**

**Main Office**: Somewhat accessible; no power-operated doors. The front desk is at an appropriate height (1300mm) for someone using a mobility device.

**Library**: Somewhat accessible; no power-operated doors.

Cafeteria: N/A

General Purpose/Gymnasium: Somewhat accessible; no power-operated doors.

There is no access to the stage.

Auditorium: N/A

Pool: N/A

**Washrooms:** This school has seven accessible washrooms in total, five on the first floor and two on the second floor.

# **Other Information**

- No visual fire alarms.
- No markings on stairs for people with low vision.

Date of Update: July 2021 Page 4 of 11



### Legend



**Exterior door**: entrance numbers on a square yellow sign.



Ramp



**Intercom**: electrical device that allows two-way communication with the main office.



**Stairs** 



**Level entrance:** entrance without stairs/steps.



Recommended pathway for disabled individuals. Power-operated door may or may not be present.



**Stepped entrance:** entrance with stairs/steps.



**Embedded photo**: click this icon on the drawing to view a photo of the area.



**Area of safe refuge**: location in a building for disabled occupants to go during a fire alarm as part of the evacuation process.



Floor level accessible by steps or stair.



Doorway



Various instructional administrative service rooms.



Elevator/lift



Main entrance



Recommended washroom (male/female) for disabled individuals



Accessible parking




Power-operated door



Bus stop

Date of Update: July 2021 Page 5 of 11







Chief Dan George Public School Facility #: 0311

Date of Update: July 2021



# **Using the Accessibility Drawings**

### Introduction

The TDSB has produced drawings to show accessible features as well as barriers for each of its buildings. This information will be useful for students, staff, parents, and community members some of whom have physical disabilities and need to know the features and barriers of our buildings.

The current Ontario Building Code (OBC) is generally used as the basis for the accessibility features included in the drawings. However, features that do not fully conform to current regulations are nevertheless identified. A legend noting features such as power-operated doors and elevators accompanies each set of drawings.

#### **Entrances**

Entrance numbers are provided on the drawings for reference and correspond to numbers posted inside and outside each public entrance. Entrance numbers have an associated icon: (denoting a flush condition) or (denoting a stepped condition). The approach to a flush entrance may be ramped, sloped, or flat, but has no appreciable height differential at the doorway. A stepped entrance is one with an appreciable step not compliant with OBC requirements for level access. Power-operated doors, if present, are identified with an icon.

To ensure student safety and security, elementary school buildings have a locked door policy. Visitors are directed to enter through the building's main entrance door after contacting the main office using the intercom provided. Where applicable, the drawings will indicate a recommended path to the main entrance doors (i.e., an arrow pointing to the main door).

A recommended path has **not** been shown **to** the main entrance where:

Date of Update: July 2021 Page 7 of 11



- the main entrance is not level, or
- the path to the main entrance has a barrier.

If a level path exists between the parking lot and a nearby level entrance, the path to the parking lot from that doorway is indicated on the drawings regardless of whether there is a power-operated door present.

At secondary schools, intercoms are not present. Usually the doors closest to the parking lot or the main entrance doors are open during school operating hours. Recommended paths are shown to these doors if the path and doorway are level and there is a power-operated door present.

#### **Interior Access**

The 1st floor (at grade) of the school is assumed to be accessible, even if there is no recommended path to the building. Access to floors other than the 1st floor is indicated by an icon denoting an elevator or ramp if present. Stairway locations are highlighted on the drawings to indicate access to floor levels; this information is included for individuals who do not require the use of a mobility device.

The main office, community-use areas, and rotation-program areas are labelled on the floor plans for ease of navigation. Various instructional, administrative, and service rooms are also indicated.

Doors at corridors and stairwells are marked on the drawings. If a power-operated door is not present (icon is absent), the doors may present a barrier to some individuals. Power-operated door devices may be push-button, hold-open, or motion-detection types.

Date of Update: July 2021 Page 8 of 11



#### **Washrooms**

Washrooms that are moderately to highly accessible are recommended and identified by a icon. The respective use for gender is also provided; male, female, or universal is denoted by a corresponding letter M, F or M/F.

# **Fire Safety Planning**

Areas of Safe Refuge are locations where persons with disabilities begin their vertical-descent stage of evacuation upon fire alarm. These have been identified on the drawing where present. They are located at EXIT stairwell landings on floors other than those at grade level, where the stairwell doors latch. Information regarding the use of Areas of Safe Refuge is found within each site's Fire Safety Plan.

# **Accessibility Designations**

The following definitions of accessibility at TDSB sites focus on mobility. Where accommodations exist for people with limited sight and/or hearing, or other types of disabilities, they will be described on each site's accessibility profile. Because each person's requirements are unique, the designation is to be used as a guideline only.

Date of Update: July 2021 Page 9 of 11





#### **Accessible**

A person who uses a mobility device can enter and move through the building to access all or most areas without assistance or with minimal assistance. To be deemed accessible,

- the building can be accessed by a barrier-free path,
- there is at least one level entry at a main entrance operated by a power-operated door,
- there is at least one barrier-free universal washroom on the main floor, and
- where the building has more than one level, there is an elevating device (such as a lift or passenger elevator), but access on all floors may be limited.



#### **Somewhat Accessible**

Somewhat accessible is our designation for buildings that are not fully accessible, but they are also not completely inaccessible. They have some features that make them partially accessible.

In a somewhat accessible building, a person who uses a mobility device can enter and move through the main floor of the building with minimal assistance. Barrier-free access to other floors is not guaranteed. Generally speaking, to be deemed somewhat accessible,

- the building can be accessed by a barrier-free path and there is at least one level entry to the building, which may or may not have power-operated doors, and
- there is at least one washroom that is somewhat barrier free.

Date of Update: July 2021 Page 10 of 11





### **Not Accessible**

A person who uses a mobility device will either not be able to access the building or will require significant assistance. To be deemed not accessible,

- the building cannot be accessed by a barrier-free path,
- there are no main entrances that are level, or
- there are no washrooms that are as a minimum, somewhat accessible.

Date of Update: July 2021 Page 11 of 11